801 E Mission Rd, San Marcos CA 92069 P: 760-744-0125 F: 760-744-6081 www.sullinscorp.com

DOC QF-7.3.7 Rev -

10/27/2010


## **ENGINEERING CHANGE BULLETIN # 10017**

Date Change Effective: 11/15/2013 Part number: LPPCxx2KFMS-M423RC

Drawing number: 11944 rev C

Explanation of configuration change:

Insulator stacker has been changed from Fig. 1 to Fig. 2.



Configuration impacts for fit, form, and function are: None

Existing parts will remain active for purchase? Yes \_\_ No \_\_x\_\_

New or revised parts are interchangeable to the previous part applications? Yes X No \_\_\_\_

Engi	neerin	a An	proval:
Lingi	11001111	y AP	DIOVAI.

Date: 11/15/2013

Russell Cody

(Signature)

Distribution: Sales/Purchasing/Manufacturing Operations/Quality Assurance/Document Control/Technical Support/Customers