


Product Change Notification #10049**Date:** 5/7/2023**Notification of:** Increased Standoffs from 1 to 4 on the termination side of the male header.**Date Change Effective:** 6/1/2023**Explanation of change (from, to):****Reason for change:** Improvement on the 1 & 2 positions (cut) header sit flat on the PCB.**Anticipated impact on fit, form, or function (positive/negative):** Positive.**Parts/Products affected:**

__C__D(AA, AB, AC, AD, AE, AF, AG, AH, AI, AJ, AK, FA, FB, FC, FD, FE, FF, FG, FH, FI, FJ, ZA, ZB, ZC, ZD, ZI, ZJ, ZO, ZQ, ZR)N - OMIT, M500, M594 (drawing # C10419)

__C__D(BA, BB, BC, BD, BE, BH, BI, BJ, GA, GB, GE, GF)N-M71, M509, M595 (drawing # C11028)

__C__D(AB, FB, ZS, ZT)N-M30, M508, M596 (drawing # C10059)

__C__DZSN-M684 (drawing # C14023)

Parts prior to the change will remain active for purchase?Yes ____ No x**New or revised parts are interchangeable to the previous part applications?**Yes x No ____**Engineering Approval:**

Truong Tran

5/8/2023

(Signature)

(Printed Name)

(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: www.sullinscorp.com/techcenter. If you have any questions or concerns, please contact us at Support@sullinscorp.com or call us at (760) 744-0125.

Sincerely,

Sullins Connector Solutions