


Date: 8/14/2023

PRODUCT CHANGE NOTIFICATION #10050**Notification of:** Molded key between position .050" pitch connectors.**Date Change Effective:** 8/14/2023.**Explanation of change:**

1. Added a gap at the molded key between position.

**Reason for change:**

1. Improvement insulator quality and moldability.

Anticipated impact on fit, form, or function: None**Parts/Products affected:** .050" pitch connector with molded key between positions.

Part number: __B__DH__

Part number: __B__DY__

Parts prior to the change will remain active for purchase? Yes.**New or revised parts are interchangeable with the previous part applications?** Yes.**Engineering Approval:**

(Signature)

Truong Tran

(Printed Name)

8/14/2023

(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: www.sullinscorp.com/techcenter. If you have any questions or concerns, please contact us at Support@sullinscorp.com or call us at (760) 744-0125.

Sincerely,
Sullins Connector Solutions