



ENGINEERING CHANGE BULLETIN # 10008

CUSTOMERS' NOTIFICATION OF PART NUMBER CHANGE

Date Change Effective: 4/5/2012

Explanation of change from existing to new update:

PBT material headers are not recommended for reflow processing.

CUSTOMERS' NOTIFICATION OF PART NUMBER CONFIGURATION REVISIONS

Date Change Effective: 4/5/2012

Explanation of configuration change/ (From) (To):

Part numbers listed below (PBT) are not recommended for reflow process and we removed processing temperature from drawing.

- | | |
|-------------------------------------|------------------------------------|
| PR_C__S__N-RC, ST, 11635-C | SBH11-PBPC-D__-ST-__, 11091-E |
| PR_C__D__N-RC, 11636-C | SBH11-PBPC-D__-RA-__, 11092-D |
| PR_C__S__N-M71RC, 11637-C | SFH11-P__C-D__-RA-__, 11161-D |
| PR_C__D__N-M71RC, 11639-C | SFH11-P__C-D__-RA-__-M181, 11163-C |
| xRPNxx2PMEN-M190RC, 11179-B | SFH11-P__C-D__-ST-__, 11160-D |
| P_C__D__N, (ST) 10419-F | SFH11-P__C-D__-ST-__-M181, 11162-C |
| P_C__S__N, (ST) 10436-D | |
| P_C__S__N, (RA) 10909-C | |
| P_C__D__N, (RA) 10912-C | |
| P_C__D__N-M71, 11028-C | |
| P_C__S__N-M71, 11432-B | |
| P_C__SAAR, 11110-C | |
| P_C10SAAN-M410, 11147-B | |
| SBT500-PRUC-D__-OI-BK-M351, 11580-B | |

Configuration impacts for fit, form, and function are:

PBT material suitable for manual or wave soldering only

Existing parts will remain active for purchase? Yes No

New or revised parts are interchangeable to the previous part applications?

Yes No

Engineering Approval:

Truong Tran

(Signature)

Date: 4/5/2012

Distribution:

Sales/Purchasing/Manufacturing Operations, Quality Assurance/Document Control, Technical Support/Customers