

SULLINS | MicroPlastics 760.744.0125 | fax 760.744.6081

801 E. Mission Rd. San Marcos Ca. 92069

http://www.SullinsElectronics.com http://www.Micro-Plastics.com

FORM DOC QF-7.3.7 Rev – 10/27/2010

ENGINEERING CHANGE BULLETIN

ECB#: 10005

DATE: 5/12/2011

CUSTOMERS' NOTIFICATION OF PART NUMBER CHANGE

Date Change Effective: 5/12/2011

Explanation of change from existing to new part number:

Removed T1 from part number per EWR# 1263

CUSTOMERS' NOTIFICATION OF PART NUMBER CONFIGURATION REVISIONS

Date Change Effective: 5/10/2011 Explanation of configuration change/ (From) (To):	
Part number on DWG# 11139 was changed from NRPCSAAN-TSAAN-RC	_
Part number on DWG# 11252 was changed from NRBCDFAN-TDFAN-RC	1RC to NRBC_
Configuration impacts for fit, form, and function are: N/A	
Existing parts will remain active for purchase? Yes: X No	
New or revised parts are interchangeable to the previous part ap Yes: X No	plications?

Engineering Approval:

(Signature)

(Sign Distribution:

Sales/Purchasing/Manufacturing Operations, Quality Assurance/Document Control, Technical Support

Date: 5/12/11