



Date: Oct 23, 2015

PRODUCT CHANGE NOTIFICATION # 10030

Notification of: Part number discontinued with replacement.

Date Change Effective: Aug 07, 2015

Explanation of change (from, to):

Part number __B60D__-S621 (DHA, DHB) (DRAWING C10680-D) will be discontinued and replaced with __B60D__-S1962, (DHA, DHB) (DRAWING C12685-A)

Reason for change: New product P/N is configured to eliminate possible incorrect installation usage in alternate PCI applications.

Anticipated impact on fit, form, or function (positive/negative): Positive

Parts/Products affected:

PCI, .050" Pitch, RAB, no guideposts, 32 Bit, 3.3V, 60 position, (11/49)

Parts prior to change will remain active for purchase?

Yes ____ No X

New or revised parts are interchangeable to the previous part applications?

Yes X No ____

Engineering Approval:

(Signature)

Ken Stark

(Printed Name)

10.23.2015

(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: www.sullinscorp.com/techcenter. If you have any questions or concerns, please contact us at Support@sullinscorp.com or call us at (760) 744-0125.

Sincerely,

Sullins Connector Solutions