


Date: 12/12/2022

**PRODUCT CHANGE NOTIFICATION #10047****Notification of:** Connector .050" Pitch Cantilever, Contact Surface Radius & SMT Terminal Change.**Date Change Effective:** 12/12/2022**Explanation of change:**

1. Changed the contact surface radius bigger.
2. Changed the connector surface mount terminal from 2 steps to 1 step bend.

**Reason for change:**

1. Improve the durability of mating cycles from 500 up to 10,000.
2. Improve quality & productivity.

**Anticipated impact on fit, form, or function:** None**Parts/Products affected:** Connector .050" (1.27mm) Contact Center, Cantilever Type.

Part number: \_\_B\_\_DYF\_ stays the same, drawing C11422 Revision F.

Part number: \_\_B35DYF\_-S2717 stays the same, drawing C13830 Revision B.

**Parts prior to the change will remain active for purchase?** Yes.**New or revised parts are interchangeable with the previous part applications?** Yes.**Engineering Approval:**

Truong Tran

12/12/2022

(Signature)

(Printed Name)

(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: [www.sullinscorp.com/techcenter](http://www.sullinscorp.com/techcenter). If you have any questions or concerns, please contact us at [Support@sullinscorp.com](mailto:Support@sullinscorp.com) or call us at (760) 744-0125.

Sincerely,  
**Sullins Connector Solutions**