

Sullins Connector Solutions

Product Change Notification # 10048

Explanation of change (from, t	o): Card slot clearance changed from .10	00" to .075".
	00"075"	
Reason for change: Reduce the	e mating PCB tilt.	
Anticipated impact on fit, form	n, or function (positive/negative): Positi	ve
Parts/Products affected:		
RLC-G7, WLC-G7 (drawing # C1	0791)	
RLC-E5, RLC-G17, WLC-G17 (dra	awing # C10630)	
RLC-E6, WLC-E6 (drawing # C10	0449)	
Parts prior to change will rema	nin active for purchase?	tions?
Parts prior to change will rema	·	tions?
Parts prior to change will remarked Yes No _x New or revised parts are interested _x No	·	tions?
Parts prior to change will remarked Yes No _x New or revised parts are interested _x No	changeable to the previous part applica	·
Parts prior to change will remarks with remarks are interested parts are interested with a second parts are interested parts are interested with a second part and a second parts are interested with a second parts are interested with a second parts are interested with a second part and a second parts are interested with a second part and a second parts are interested with a second part and a	Truong Tran (Printed Name)	5/9/2023