

801 E Mission Rd, San Marcos CA 92069 P: 760-744-0125 F: 760-744-6081 www.sullinscorp.com

FORM DOC QF-7.3.7 Rev – 10/27/2010

ENGINEERING CHANGE BULLETIN #10024

CUSTOMERS' NOTIFICATION OF DRAWING SPECIFICATION UPDATE
Date Change Effective: 1/22/2015
Explanation of change from existing to new part number:
The 'S' plating description on the following products have been updated from "10µ in.
Gold Overall" to "10µ in. Gold on Contact Surface, Gold Flash on Termination":
SMH100-LP_E-SSBK (DWG 11190-B)
SMH100-LP_E-SRA-BK (DWG 11191-B)
SMH100-LP_E-SST-BK (DWG 11192-B)
SMH10LP_E-DSBK (DWG 11193-C)
SMH100-LP_E-DRA-BK (DWG 11194-B)
SMH100-LP_E-DST-BK (DWG 11195-B)
SMH15LP_E-DSBK (DWG 11196-B)
SMH150-LP_E-DST-BK (DWG 11197-B)
SFM210-LP_E-SSBK (DWG 11198-C)
SFM210-LP_E-SST-BK (DWG 11199-C)
SFM210-LP_E-DSBK (DWG 11200-D)
SFM210-LP_E-DST-BK (DWG 11201-C)
SBS450-NR_B-DQA-BK-M300 (DWG 11555-C)
SMH100-LP_E-SRA-BK-M298 (DWG 11582-B)
SBH51-LP_E-DST-BK (DWG 11774-B)
SBH51-LP_E-DSBK (DWG 11775-B)
Configuration impacts for fit, form, and function are:
None
Existing parts will remain active for purchase?
·
Yes X No
New or revised parts are interchangeable to the previous part applications?
Yes X No
1es <u>X</u> 110
Engineering Approval:
Ken Steek
Date: 01.22.2015
(Signature)
Ken Stark
(Printed Name)

Distribution:

Sales/Purchasing/Manufacturing Operations, Quality Assurance/Document Control, Product Specialist, Molding, Kitting