

SULLINS | MicroPlastics 760.744.0125 x 102 | fax 760.744.6081 801 E Mission Rd San Marcos CA 92069 http://www.Sullinscorp.com

PCN: 10001

January 14, 2010

CUSTOMERS' NOTIFICATION OF DIMENSIONAL CHANGE

Effective immediately, the pin height dimension for the Male Header Connector part numbers $__N$ $__2MAMS-RC$ is changed as shown below:

.079" [2mm] CONTACT CENTERS, SMT MALE HEADER


FROM: (Figure 1)

TO: (Figure 2)

DIMENSIONAL CHANGE:

.157" [4.00]

.142" [3.60]








Figure 2

REASON FOR CHANGE:

To enhance the mating between the male and female header connectors. Sullins part numbers will remain unchanged

ANTICIPATED IMPACT ON FIT, FORM OR FUNCTION:

Positive - Backwards Compatible

IDENTIFICATION:

None

Tom Huynh

Engineering Manager